


HEADQUARTERS
PHILIPPINE ARMY
OFFICE OF THE ARMY QUARTERMASTER
Fort Andres Bonifacio, Metro Manila

UNDERSHIRT, RAGLAN, POLYESTER SPANDEX, ROUND NECK
QM SPEC NR IC-21USRRN dtd 27 May 2019

VISUAL INSPECTION CHECKLIST

DESCRIPTION OF DEFECTS	CLASIFICATION OF DEFECTS
1. Packing and Packaging	
a. Each undershirt shall be placed in a transparent (cellophane) bag.	Minor
b. Each bag shall have a markings as shown in the specification printed legibly on one face at the center portion of the bag using black indelible ink	Major
c. One Hundred (100) pieces of T-Shirt of the same sizes shall be packed in a corrugated carton.	Major
d. The top cover when closed shall be sealed with a binding tape and finally secured with nylon straps.	Minor
e. Contents of carton label shall be as specified	Minor
2. Shall be a combination of Olive Drab and Olive Drab with design	Major
3. The basic material of the collaret shall be the same with the fabric of the back part	Major
4. ARMY Marking:	
a. Shall have an ARMY Marking	Major
b. Placed at the left breast part of the T-Shirt using black ink	Major
5. The undershirt shall be of the men's pull over athletic type and of a design essentially the same as the official sample of the Philippine Army	Major
6. Loose sewing/Untrimmed thread ends	Minor
7. Contractor's label and Washing Instruction	
a. Printed on the inside back portion of the T-Shirt using black paint	Major
b. Contents of the label shall be as specified	Major
8. Presence of dirt, stains and other defects:	
a. Affecting appearance	Major
b. Does not affect appearance	Minor

Note: Finished undershirts shall conform with the illustration and the Official sample of the Philippine Army. Any discrepancy shall be considered as ground for non-acceptance.


EDMUNDO S SUFICIENCIA
Colonel, QMS (GSC) PA
Chief